### **CASE** STUDY

## **Tensar**

**PROJECT** Northpointe Subdivision

LOCATION Plainfield, IL

OWNER Village of Plainfield

**CONTRACTOR** Pulte Group, Inc.

SUB-CONTRACTOR Orange Crush, LLC

**ENGINEER** Village of Plainfield

**INSTALLATION DATE** November 2018

#### **PROJECT DETAILS**

Contractor encountered soft soils during excavation. Due to cold weather, the Village of Plainfield does not allow lime stabilization after October 15<sup>th</sup>. A Tensar representative visited the site and determined the subgrade CBR to be 2%. A solution using TX5 Geogrid required no undercut to stabilize the subgrade and allow the construction of the pavement section on top.



#### PRODUCT

TriAx® TX5 Geogrid 10,400 SY



#### TIME SAVINGS

Allowed construction to continue through cold weather conditions





### **CASE** STUDY

# **Tensar**<sub>®</sub>



Tensar International Corporation, 2500 Northwinds Parkway, Suite 500, Alpharetta, GA 30009 | TensarCorp.com | 800-TENSAR-1